

FICHA TÉCNICA



MIG - MAG

XD400 M CC/CV

MULTIVOLTAJE AUTOMATICO

- PROCESOS DE TRABAJO PESADO
TRIFÁSICA TIPO INVERSOR



CARACTERÍSTICAS DE MÁQUINA

INPUT VOLTAGE (V)	INPUT CURRENT (A)	POWER RATING (KVA)	OCV (V)	WELDING CURRENT (A)
AC 220/380/440±15%	37.5	20.7	72	50 - 400
DUTY CYCLE	WEIGHT (KG)	DIMENSION (MM)	GMAW VOLTAGE (V)	WIRE DIAMETER APPLICABLE (MM)
60%@400A/40V 100%@370A/33V	60	606*276*449	15 - 40	Ø (0.8 - 1 - 1.2-1.6)



ACCESORIOS INCLUIDOS



Guantes
de soldar



Antorcha MIG



Tierra con
cable.



Porta-Electrodo
con Cable.

ACCESORIOS QUE NO INCLUYEN



Regulador
de gas



Cilindro



Mascara
de soldar

● TRABAJO
LIVIANO

● TRABAJO
SEMI-PESADO

● TRABAJO
PESADO

