

FICHA TÉCNICA



MMA

ARC 500E MT

MULTIVOLTAJE AUTOMATICO

- PROCESOS DE TRABAJO SEMIPESADO
TRIFASICO TIPO INVERSOR



CARACTERÍSTICAS DE MÁQUINA

INPUT VOLTAGE (V)	INPUT CURRENT (A)	POWER RATING (KVA)	OCV (V)	WELDING CURRENT (A)
AC 220/380/440 $\pm$ 15%	66.40 /32.2/ 32.2	25.3	78	20 - 400 20 - 500 20 - 500
DUTY CYCLE		WEIGHT (KG)	DIMENSION (MM)	
220V	380 - 440V	31	680*410*575	
60%@400A/36V	60%@500A/35.2V			
100%@300A/30V	100%@350A/32.5V			



ACCESORIOS INCLUIDOS



Guantes
de soldar.



Tierra con
cable.



Porta-Electrodo
con Cable.

ACCESORIOS QUE NO INCLUYEN



Regulador
de gas



Cilindro



Mascara
de soldar

○ TRABAJO
LIVIANO

● TRABAJO
SEMI-PESADO

○ TRABAJO
PESADO

